

Solution	Marks
<p>Q.2 a. What is meant by hysteresis? Explain the terms retentivity and coercivity</p> <p>Ans 2 a. Refer 1 - 8 (8.9)</p> <p>b. A mild steel ring having a cross-sectional area of 500 mm² and a mean circumference of 400 mm has a coil of 200 turns wound uniformly around it. Calculate:</p> <p>(i) The reluctance of the ring and</p> <p>(ii) The current required to produce a flux of 800 μwb in the ring. Assumed the relative permeability of mild steel to be 380.</p> <p>b. (a) the reluctance of the ring is given as</p> $S = \frac{1}{\mu_0 \mu_r} \cdot \frac{l}{A} = \frac{0.4}{380 \times 4\pi \times 10^{-7} \times 500 \times 10^{-6}}$ $= \underline{1.675 \times 10^6 \text{ A/wb}} \quad \textcircled{4} \quad \underline{\text{Ans}}$ <p>(b) We know that</p> $F = \phi S = 800 \times 10^{-6} \times 1.675 \times 10^6 = 1340 \text{ A} \quad \textcircled{2}$ $\therefore \text{Magnetising current} = I = \frac{F}{N} = \frac{1340}{200} = \underline{6.7 \text{ A}} \quad \textcircled{2} \quad \underline{\text{Ans}}$	8

Q.3a. Explain how various losses in a transformer can be found from practical tests without actually loading the transformer.

8

Refer [9(9.8)]

b. A 10 – kVA, 200V/400V, 50 Hz, single-phase transformer gives the following test result:

Open-circuit test (HT windings open-circuited): 200V, 1.3A, 120W.

Short-circuit test (LT winding short-circuited): 22V, 30A, 200W.

Calculate (i) the magnetising current and the current corresponding to core loss at normal circuit as referred to LT winding.

b. (i) Given : $W_0 = 120\text{W}$; $V_0 = 200\text{V}$; $I_0 = 1.3\text{A}$

$W_{sc} = 200$; $W_{sc} = 200\text{W}$; $V_{sc} = 20\text{V}$; $I_{sc} = 30\text{A}$

$$I_w = \frac{W_0}{V_0} = \frac{120}{200} = 0.6\text{A}$$

Ans.

$$I_m = \sqrt{I_0^2 - I_w^2} = \sqrt{1.3^2 - 0.6^2} = 1.15\text{A}$$

Ans.

(ii) $R_0 = \frac{V_0}{I_w} = \frac{200}{0.6} = 332\Omega$

Ans

$$X_0 = \frac{V_0}{I_m} = \frac{200}{1.15} = 174\Omega$$

Ans.

If we designate the LT winding as winding 1 and HT winding as winding 2, we get

$$R_{02} = \frac{W_{sc}}{I_{sc}^2} = \frac{200}{30^2} = \underline{0.222\Omega} \quad \text{Ans}$$

$$Z_{02} = \frac{V_{sc}}{I_{sc}} = \frac{22}{30} = \underline{0.733\Omega} \quad \text{Ans}$$

$$X_{02} = \sqrt{Z_{02}^2 - R_{02}^2} = \sqrt{0.733^2 - 0.222^2} = \underline{0.699\Omega} \quad \text{Ans.}$$

Here, the turn ratio, $k = \frac{V_1}{V_2} = \frac{400}{200} = \frac{1}{2}$

The equivalent resistance and reactance as referred to LT windings are

$$R_{01} = k^2 R_{02} = \frac{0.222}{4} = \underline{0.055\Omega} \quad \text{Ans}$$

$$X_{01} = k^2 X_{02} = \frac{0.699}{4} = \underline{0.175\Omega} \quad \text{Ans.}$$

Q.4 a. Draw the power flow diagram for a dc. Motor and explain it.

8

Refer 1 [11(11.10)]

- b. A 6-Pole, lap-connected armature with 864 conductors dc motor takes an armature current of 110A at 480V, the armature circuit has a resistance of 0.2Ω. The flux per pole is 0.05Wb. Calculate:
- The speed
 - The gross torque developed by the armature

8

b. (i) Generated emf $E_a = 480 - [110 \times 0.2] = 458 \text{ V}$ — (2)

Given $\phi = 0.05 \text{ Wb}$; $Z = 864$; $P = 6$, $A = 6$

We know that $E_a = \frac{\phi Z N P}{60 A}$

$$N = \frac{60 A E_a}{\phi Z P} = \frac{60 \times 6 \times 458}{0.05 \times 864 \times 6} = 636 \text{ rpm Ans}$$
 — (3)

(ii) We know that $E_a L = \frac{2\pi N T}{60}$

$$T = \frac{E_a 160}{2\pi N} = \frac{458 \times 110 \times 60}{2 \times \pi \times 636} = 756 \text{ Nm Ans}$$
 — (3)

- Q.5 a. Explain the effect of change in excitation of a synchronous motor on**
- its armature current
 - its power factor

8

5a. Refer 1 [12 (12.2)]

- b. State the advantages of having rotating field system rather than a rotating armature system in a synchronous machine.**

b. Refer 1 [12 (12.2)]

8

Q.6 a. Prove that the frequency of the rotor induced emf in an induction motor is slip times the stator supply frequency.

8

Refer 1 [12 (12, 3)]

b. A three-phase, 6-pole, 50Hz induction motor develops maximum torque at a speed of 940 rpm. If the rotor resistance per phase is 0.1Ω , determine the stand still rotor reactance.

b. The synchronous speed is given as

$$N_s = \frac{120f}{p} = \frac{120 \times 50}{6} = 1000 \text{ rpm} \quad (2)$$

$$\therefore \text{slip, } s = \frac{N_s - N}{N_s} = \frac{1000 - 940}{1000} = 0.06 \quad (2)$$

We know that maximum torque occurs at a slip

so as to satisfy the condition $R_2 = sX_{20} \quad (2)$

$$X_{20} = \frac{R_2}{s} = \frac{0.1}{0.06} = 1.66\Omega \quad \text{Ans. } (2)$$

Q.7	Write short notes on any <u>TWO</u> :	8x2
	(i) Shaded pole motor (ii) Hysteresis motor (iii) Universal motor	
	<i>Q.7 Refer 1 [13 (13.2 + 13.4)]</i>	
Q.8	a. With the help of a neat diagram explain the function of various components of a thermal power plant.	8
	<i>a. Refer 1 [15 (15.3)]</i>	
	b. With the help of a neat diagram explain the layout for a storage type hydro power plant.	8
	<i>b. Refer 1 [15 (15.5)]</i>	
Q.9	Write short notes on the following:	
	(i) HVDC Transmission (ii) Energy Storage	8x2
	<i>Q.9. Refer 1 [15 (15.13 + 15.15 + 15.16)]</i>	
	<i>E₁ : Refer 1 [15 (15.6 + 15.11 + 15.12)]</i>	
	<i>E₂ : Refer 1 [15 (15.16 + 15.4)] 1 [13 (13.2)]</i>	

TEXT BOOK

1. Basic Electrical Engineering, D.P. Kothari and I. J. Nagrath, Tata McGraw-Hill Publishing Company Limited, 2nd Edition, 13th Reprint 2006